



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

May 20, 2008

Supervisor LA

<b>Mine Name:</b> Bright 1&2	<b>Permit Number:</b> M210030
<b>Operator Name:</b> Scott Holt	<b>Inspection Date:</b> April 23, 2008
<b>Inspector(s):</b> Tom Munson	<b>Time:</b> 2:00-3:00PM
<b>Other Participants:</b> none, workers on site	<b>Mine Status:</b> active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

To visit the site and determine what changes had occurred since last inspection.

#### Inspection Summary:

Arrived onsite and determined that the site was active. The workers were maintaining stockpiles of crushed material and the two quarries were not actively being mined. The material that had been mined was crushed and sorted into various sized materials for sale. The site was clean and organized and no trash or other deleterious materials were noted during the inspection.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature

TM:pb

cc: (OPERATOR)

cd\_ginouves@blm.gov

O:\M021-Iron\M0210030-Bright1&2\Inspections\04232008insp.doc

080004